Avon Township Road Inspection – 2017

Date of inspection: April 22, 2017

Present: Richard Bresnahan, John Merdan, Joe Koopmeiners, Stephen Saupe, and LeRoy

Notes / Observations
Road in bad shape; water washing across end of road, Koopmeiners will dig it out to provide better drainage
Remove ash tree near cul-de-sac (tree service)
Remove overhanging limb; remove tires and trash along road; 36932 – driveway needs culvert because water is backing up, send letter to resident to request action
Rubberize cracks (9)
Remove large poplar tree (tree service); fill hole; remove overhanging branches; sinkhole needs fill
Rubberize cracks (22); large crack in cul-de-sac
Fix hole near intersection with St. Anna Dr.
Fix hole near intersection with Norway
Send resident letter to move row of pines in ROW, need to move them about six feet from the road; remove cottonwood at cul-de-sac (call Xcel)
Remove dead oak at cul-de-sac
Add 3 loads of gravel
Add 1 load of gravel
Gravel on shoulder by Queens
Culvert collapsing – on N side of road, remove sediment impeding drainage; S

	side – needs to be excavated, about 10 long culvert section added, then filled and filled. Koopmeiners will complete when it is dry
363 rd St.	and filled. Koopmeiners will complete when it is dry
303 3t.	
365th St.	
365 th (min)	
370th St. (W of 155; min. maint.)	Needs class 5, rocks poking through
370th St. (off Co Rd 9)	Finish trimming back cedars
370th St. (E of	Remove leaning trees
155) 377 th St.	Patch at cul-de-sac
Named Roads	
Cardinals Nest	
Highland Terrace	Patch near Shorewood (50 ft, no blanket); Contact company to fix pothole near 33706
Koppy Lane	Dirt pile on cul-de-sac a problem with lots of snow; patch (and blanket) needed (50 ft)
Lower Spunk Lane	Remove 2 trees by 34213 (tree service); brushing
Meadowview Road	If road needs to be plowed for legal reasons, Koopmeiners can use pickup with blade raised once main plowing has been completed; water in ditch appears to be flowing well; remove trash; spread 4 loads of gravel
Narnia Lane	Cold patch holes near Co Rd 9
Nob Hill Drive (S)	Cold patch hole; Gravel needed on approach
Nob Hill Drive (north)	Gravel needed on approach
Noble Oak Circle	Gravel on shoulder
Nordica Road	
Norman Road	Crack on cul-de-sac
Norway Road	Cold patch on corner W of Meadowview; remove trees by curve; road in rough shape; remove plums near 14564
Orchid Court	Move 911 sign
Parkwood Circle	Class 5 on shoulder by entrance from Co Rd 9; Brush by Plum Hill; 15603 – remove metal edging and six bricks, add fill, move mailbox back 18 inches & use breakaway post; 15636 – residents should remove brush pile; brushing in several areas; Patch (160 ft) to fix frost heave near 15522 (needs fabric).
Peach Drive	DNR will likely make residents (34392) remove sandy access they created to the SNA pond, send letter about protecting the Town road; shouldering
Pelican Lake Road	Shouldering near 360th

Plum Hill Lane	Straighten signposts; cul-de-sac cracking, will eventually need replacing
Princewood Road	Cold patch by Co Rd 159
Quaker Road	Shouldering near Tower Rd
Queens Road	Rubberized recently but will need to be resurfaced; remove leaning trees near 160 th and bridge (some will require tree service); water backing up from beavers or bog that broke loose, will need to be cleared, contact DNR
Red Maple Drive	Patch frost boil; Road alignment checked, no work is recommended at this time
Red Oak Circle	
Riley Court	Class 5 on shoulder
Sara Lane	
Shorewood Drive	Crumbling near end; 33401 – remove mailbox on road, interferes with plowing
Springwood Lane	
Spunk Tree Circle	
St. Anna Drive	Examined burned area W of Larkey's, no action necessary
Sunnyfield Circle	Resident (19297 Two Rivers) raked rock onto Sunnyfield
Tower Road	Rough near entrance; Larson drive requires aprons and may be too wide
Two Rivers Road	No water issues noted on Breth/Streit properties; Patches near 19354
Upper Spunk Lake Road	Some cracking noted; Nothing can be done for water/gravel washing into drive (17083); Tree removal project – contractor did an excellent job; 17679 – brush around No Parking Sign; 17927 – remove leaning trees; 17857 – remove dead elms; 17749 – remove leaning tree; 17545 – basswood leaning over road; remove cement curbing at Co Rd 9; 17679 – resident proposes to run line under road to a new drain field, an encroachment agreement will need to be prepared; continue removing little trees
General Comments	Yellow plow truck has a leak in the gas tank, the bed is rusty, hydraulics problematic, etc. A truck in better shape is available for about \$26,000.